

## **2/10/12- Summary of Residences with Methane Results Exceeding the EPA Trigger of 28,000 (ug/L)**

### HW-12 (sampled 1/26/12) - Methane = 52,000

- 1) Included in CO&A group? Yes
- 2) Well vented? Need to check w/START
- 3) Sample collected from well or tap? Sample collected at well in treatment shed - prior to air pressure tank and any treatment. Well not connected to residence at time of sampling. Residence being provided with bulk water from Cabot. Water buffalo in basement.
- 4) Methane system installed? Yes, well has Cabot installed treatment shed/system which includes 2 methane strippers. However, system not fully functional at time of sampling Cabot was still testing the system.

### HW-25-P (sampled 1/30/12) - Methane = 65,000

- 1) Included in CO&A group? No
- 2) Well vented? Yes
- 3) Sample collected from well or tap? Tap only
- 4) Methane system installed? No

### HW-26 (sampled 1/31/12) - Methane = 43,000

#### HW-26 P (P=Tap sample) = 38,000

- 1) Included in CO&A group? No
- 2) Well vented? Need to check with START
- 3) Sample collected from well or tap? Both well and tap collected, P=tap (Will need to confirm w/START)
- 4) Methane system installed? Need to check w/START

### HW-29 (sampled ) - Methane = 77,000

#### HW-29z (z=duplicate ) - Methane = 62,000

- 1) Included in CO&A group? No
- 2) Well vented? Yes
- 3) Sample collected from well or tap? Well had been disconnected from residence prior to sampling. Residence being provided with bulk water from Cabot. Water buffalo in garage. Well was temporarily connected to residence in order to collect well sample. Sample collected from well just after pressure tank in garage.
- 4) Methane system installed? No